City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 1 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 12/03/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S03AA1013MH	Test ID: S1032-026014	Notifications (Residents, Fire, 311) : Yes


Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date : <u>12/03/2008</u>
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S03AA1013MH	Test ID: S1032-026014	Notifications (Residents, Fire, 311) : Yes

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Main Sewer; Smoke: Medium; Status: Public ROW

Landscape




Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 3 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date : <u>12/03/2008</u>
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S03AA1013MH	Test ID: S1032-026014	Notifications (Residents, Fire, 311) : Yes

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Light; Status: Private Property

Defect



Landscape




Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 4 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: <u>12/03/2008</u>
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : Ryan Lamont
Manhole ID: S03AA1013MH	Test ID: S1032-026014	Notifications (Residents, Fire, 311) : Yes

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property

Landscape



Defect

